

State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple, Suite 1210 Michael O. Leavitt

801-538-7223 (TDD)

Governor Kathleen Clarke

Executive Director Lowell P. Braxton Division Director

PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax)

INSPECTION REPORT

Partial: Complete: X Exploration:
Inspection Date & Time: July 13, 1999
Date of Last Inspection: June 17 and 30, 1999
Mine Name: Gordon Creek Mines 2, 7 & 8 County: Carbon Permit Number: ACT/007/016
Permittee and/or Operator's Name: Mountain Coal Company
Business Address: P.O. Box 591 Somerset, Colorado 81434
Type of Mining Activity: Underground X Surface Prep. Plant Other
State Officials(s): David Darby
Company Official(s): None
Federal Official(s): None
Weather Conditions: Clear, warm
Existing Acreage: Permitted- 2289 Disturbed- 0 Regraded- 17.2 Seeded- 17.2 Bonded- 17.2
Increased/Decreased: Permitted Disturbed Regraded Seeded Bonded
Status: _Exploration/X_Active/_Inactive/_Temporary Cessation/_Bond Forfeiture
Reclamation (_Phase I/_Phase II/_Final Bond Release/_Liability_Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.

 a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
- b. For <u>partial inspections</u> check only the elements evaluated.

 Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

				001000	N KON KATA IIT
1	DEDMITE CHANCE TRANSFER DENEWAL CALE	EVALUATED	<u>N/A</u>	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE SIGNS AND MARKERS	[X]	H	[X] [X]	71
2.		[X] [X]	뷰	[] [<u>\V</u>]	Ħ
3.	TOPSOIL	IΔI	Ц	Ц	н
4.	HYDROLOGIC BALANCE:	rw1	гэ	rv1	г 1
a.	DIVERSIONS	[X] [X] [X] [X] [] []			
b.	SEDIMENT PONDS AND IMPOUNDMENTS		H	H	H
C.	OTHER SEDIMENT CONTROL MEASURES		H	H	H
ď.	WATER MONITORING		H	H	H
e.	EFFLUENT LIMITATIONS	ĮΔJ	LVI	H	Η
5.	EXPLOSIVES	빉	IXI IXI	H	片
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	H	뗁	<u> </u>	니
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	Ц	ည	붜	片
8.	NONCOAL WASTE	[X]	Ц	П	ш
9.	PROTECTION OF FISH, WILDLIFE AND	£373	r 1	r 1	F.3
	RELATED ENVIRONMENTAL VALUES	[X] [X] [X] [X] [X] [X]			片
10.	SLIDES AND OTHER DAMAGE	<u>IXI</u>	Ц	H	片
11.	CONTEMPORANEOUS RECLAMATION	IXI	Ц	H	H
12.	BACKFILLING AND GRADING	<u>[X]</u>	Ц	Ц	H
13.	REVEGETATION	<u>IXI</u>	Ц	H	H
14.	SUBSIDENCE CONTROL	X	Ц	Н	붜
15.	CESSATION OF OPERATIONS	<u>[X]</u>	Ц	П	Ц
16.	ROADS:			F.1	F.3
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[X]		Ħ	H
b.	DRAINAGE CONTROLS	[X]	Щ	Ц	H
17.	OTHER TRANSPORTATION FACILITIES	П	<u>[X]</u>	Ц	Ц
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	П	<u>[X]</u>	Щ	Ħ
19.	AVS CHECK (4th Quarter-April, May, June)(date)	Ц	Ц	Ц	Ħ
20.	AIR QUALITY PERMIT	П	ΙΧΙ Π	Ц	Ħ
21.	BONDING & INSURANCE	[X]	Ц	Ц	П

INSPECTION REPORT

(Continuation sheet)
PERMIT NUMBER: ACT/007/016

Page <u>2</u> of <u>4</u> DATE OF INSPECTION: July 13, 1999

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS

Chris called on July 8, and left a message, a backhoe had been mobilized to the Gordon Creek #2 Mine for mitigation work caused by trespassers. I called Dan Guy on July 9, to let him know I could not get down to the site until Tuesday of the following week.

Mitigation work was conducted for two reasons by the operator. Trespassers contributed to some damage to the reclamation project and calculation of as-built designs identified that the channel was too small if antecedent moisture conditions prevail. The major portion of the mitigation work was completed on Monday, July 12. I arrived on Tuesday. The backhoe was still on site, but not being used. One young man was on site collecting riprap to reenforce the channels. He told me he had been picking up debris earlier that day. I asked if anyone was spraying for thistle, he told me a couple of people were on site a couple days earlier spraying and cutting the weeds.

I checked the mitigation work conducted by EIS against the list of repair projects we compiled on the last inspection. The following activities were found.

1. Excavate or build up the embankment on Channel SD-5

The contractor reconstructed the channels giving them more depth. This modification was the result of my comments to size the channel to accommodate the design flows under antecedent moisture condition III. Riprap was laid in the bottom of SD-5 but not along the side slope. I mentioned to Mel Coonrod, who was driving to the site, that the riprap would work better if it was placed on the slope of the channel. The channel has a substrate of rocks mixed with dirt from previous construction that should provide protection from erosion. Mel stated he would have his worker move the riprap from the bottom of the channel and use it to reenforce the embankment.

2. Regrade the areas where were ruts were left by the vehicle.

The slope where the vehicle had gained access and created ruts was gouged using the backhoe bucked. The gouges were not as deep as those smoothed out by the landowner, but were rough enough to restrict access by vehicles. Dan Guy had mentioned earlier that the gouged area shouldn't need to be revegetated because there were still live plants in between the gouges and native seeds would blow into the area.

3. Build a berm or cut a small diversion across the slope by the lower fence that directs runoff into the upper sedimentation pond cell.

The contractor constructed a small ditch and berm paralleling the access fence to collect and divert any runoff flowing down the slope of the reclaimed access road. Runoff reaching the ditch will be directed into the upper cell of the sedimentation pond.

Copy of this Report:

Mailed to: <u>James Fulton (OSM/Denver)</u>, <u>Chris Hansen (CFC)</u>, <u>Dan Guy (Blackhawk Engineering)</u> Given to: <u>Joe Helfrich (DOGM)</u>

Inspector's Signature: David Darby #47 Date: August 6, 1999

Page 3 of 4 DATE OF INSPECTION: July 13, 1999

(Comments are Numbered to Correspond with Topics Listed Above)

4. Replace the boulders that were moved by the trespasser to gain access.

The contractor replaced the boulders across the access site.

5. Repair the fence around the property.

The contractor repaired the fence across the access site, however it looked like it could be reenforced some. There were no cattle on site.

6. Continue to treat the thistle growing on the property.

One young man was on site collecting riprap to reenforce the channels. He told me he had been picking up debris earlier that day. I asked if anyone was spraying for thistle, he told me some people were on site a couple days earlier spraying and cutting the weeds.

7. Remove the remaining mining debris that was missed on previous cleanup, such as wires, brattice, a crushed culvert and a crushed gabion basket

The young man on site told me that the culvert and gabion structure above Jacob's Pond had not been removed, that they still intended to remove them.

8. Clean and repair rock weir structures along the main access road.

I checked the rock weirs. The contractor had cleaned the sediment out from behind the structures, however some of the structures needed repairs which had not been done.

Changes 1, 6, 7 and 8 were not changes required as a result of the trespass, but was needed as ongoing reclamation maintenance.

2. Signs and Markers

The signs were intact on the main entry fence identifying the minesite and "No Trespassing" status.

- 4. Hydrologic Balance
- a. Sediment Pond and Impoundments

The weather has been warm and dry. The lower two cells of the sedimentation pond were dry and the upper cell was only about one quarter full. I hiked up to the # 7 and # 8 reclaimed minesites. All channels appeared intact. Water was seeping from the springs at the #7 mine, mouth of Slide Canyon and above Jacob's Pond.

Copy of this Report:

Mailed to: James Fulton (OSM/Denver), Chris Hansen (CFC), Dan Guy (Blackhawk Engineering)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: David Darby #47 Date: August 6, 1999

Mountain Coal Company Water Monitoring Report August 1, 1999 Last Submittal in office records

UPDES 001 Sed Pond outflow N 98-06-01 to 98-06-30		N. Fk Gordon Creek	Monthly		
	2, 7 and 8 Mine Water Monit	toring			
Site	Location	Monitoring Schedule	Date Last Monitored	Condition	
2-1-W	Sediment Pond Discharge	Monthly	6-1-99	No Flow	
2-2-W	Discharge North Fork of Gordon Creek (Sweets Pond)	Quarterly	6-11-99	285 gpm Quality	
2-3-W	Lower Beaver Creek	Continuous Bi-annual quality	6-11-99	785 gpm Quality	
2-4-W	Upper Beaver Creek	FlowContinuous Bi-annual quality	6-11-99	164 gpm Quality	
2-5-W	Jewke's Spring	Bi-annual	6-11-99	314 gpm	
2-6-W	Gunnison Spring	Bi-annual	6-11-99	47 gpm	
2-7-W	Left Fork of Bryner	Quarterly	6-11-99	18.7 gpm	
2-8-W	Right Fork of Bryner	Quarterly	6-11-99	3.5 gpm	
2-9-W	Bryner Cyn. Below Mine	Quarterly	6-11-99	No Flow	
2-10-W	Inlet to Pond Jacob's	Quarterly	6-11-99	87 gpm	
2-11-W	Inlet to 3 cell Sedimentation Pond	Monthly	6-11-99	Dry	

	J&H MARSH & McL	ENN A , INC.	CERTIFICA	ATE O	SURANCÉ	CERTIFICATE NUMBER		
PRODUCER THIS CERTIFICATE IS IS NO RIGHTS UPON THE C					MATTER OF INFORMATION ON HOLDER OTHER THAN THOSE OT AMEND, EXTEND OR ALTEF HEREIN.	PROVIDED IN THE		
		<i>y</i>		COMPANIE	S AFFORDING COVERA	\GE		
arch	-GL-UT/CO-99-00		COMPANY A S					
INSU			COMPANY					
P.O.	ntain Coal Company, L.L.C. Box 591			В				
1 Mi	le East of Somerset - Hwy 133 nerset, CO 81434		COMPANY					
	·		COMPANY					
	COVERAGES This certificate supersedes and replaces any previously issued certificate. O THIS IS TO CERTIFY THAT POLICIES OF INSURANCE LISTED HEREIN HAVE BEEN ISSUED TO THE INSURED NAMED HEREIN FOR THE POLICY PERIOD INDICATED. NOTWITHSTANDING ANY REQUIREMENT, TERM OR CONDITION OF ANY CONTRACT OR OTHER DOCUMENT WITH RESPECT TO WHICH THE CERTIFICATE MAY BE ISSUED OR MAY PERTAIN, THE INSURANCE AFFORDED BY THE POLICIES LISTED HEREIN IS SUBJECT TO ALL THE TERMS, CONDITIONS AND EXCLUSIONS OF SUCH POLICIES. LIMITS SHOWN MAY HAVE BEEN REDUCED BY PAID CLAIMS.							
CO	TYPE OF INSURANCE	POLICY NUMBER	POLICY EFFECTIVE DATE (MM/DD/YY)	POLICY EXPIRATION DATE (MM/DD/YY)	LIN	IITS		
A	GENERAL LIABILITY	GL 01200289	07/31/99	07/31/00	GENERAL AGGREGATE	\$ *500,000		
^	X COMMERCIAL GENERAL LIABILITY	*\$500,000 general aggregate applie	s		PRODUCTS - COMP/OP AGG	\$ 500,000		
	CLAIMS MADE X OCCUR	per location			PERSONAL & ADV INJURY	\$ 300,000		
	OWNER'S & CONTRACTOR'S PROT				EACH OCCURRENCE	\$ 300,000		
	X Includes XCU				FIRE DAMAGE (Any one fire)	\$ 50,000 \$ 5,000		
	AUTOMOBILE LIABILITY				MED EXP (Any one person)	\$ 3,000		
	ANY AUTO				COMBINED SINGLE LIMIT	•		
	ALL OWNED AUTOS SCHEDULED AUTOS				BODILY INJURY (Per person)	\$		
	HIRED AUTOS				BODILY INJURY	\$		
	NON-OWNED AUTOS				(Per accident) PROPERTY DAMAGE	s		
					1110, 211, 31	*		
	GARAGE LIABILITY				AUTO ONLY - EA ACCIDENT	\$		
	ANY AUTO	-			OTHER THAN AUTO ONLY:	\$		
					EACH ACCIDENT AGGREGATE	\$		
	EXCESS LIABILITY				EACH OCCURRENCE	\$		
	UMBRELLA FORM		CEIVI		AGGREGATE	\$		
	OTHER THAN UMBRELLA FORM			=======================================	WC STATU- OTH	\$		
	WORKERS COMPENSATION AND EMPLOYERS' LIABILITY				TORY LIMITS ER	\$		
	THE PROPRIETOR/		UL 3 0 1999		EL EACH ACCIDENT EL DISEASE-POLICY LIMIT	\$		
	PARTNERS/EXECUTIVE OFFICERS ARE: INCL				EL DISEASE-EACH EMPLOYEE			
	OTHER DECE		DIL, GAS &	MINING				
		Div. W	The second secon	and the second second second second second				
DES	CRIPTION OF OPERATIONS/I OCATIONS/V	EHICLES/SPECIAL ITEMS (LIMITS MAY BE SUI	BJECT TO DEDUCTIBL	ES OR RETENTIONS)	<u> </u>	· · · · · · · · · · · · · · · · · · ·		
4	mit ACT/007/016, Gordon Creek M			,				
			CANCELLA	TION				
CE	RTIFICATE HOLDER				FIN RE CANCELLED REFORE THE EX	(PIRATION DATE THEREOF TH		
	SHOULD ANY OF THE POLICIES LISTED HEREIN BE CANCELLED BEFORE THE EXPIRATION DATE THEREOF, THI INSURER AFFORDING COVERAGE WILL XNUXXVVVVVVVVVVVVVVVVVVVVVVVVVVVVVVVVVV							
Utah Dept. Of Natural Resources				EREIN, BOOKKAILUNECHOO		CKRREGRESCHOOK SOKSTANDICHOOG		
Division of Oil, Gas and Mining 1594 W. North Temple			XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	MAXXIXIB XIRSXVAXIEXINAODHERARER SINBINIES ODCAEN XBEXAREX NOBACEN BARRING NAVANARA SIBER XBEXAREX SES BEXAX S				
Sui	te 1210 t Lake City, UT 84114-5801				XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXXXXX		
ا	. aano ony, or o 1114 0001			LENNAN, INCORPORA Peterfeso	<u>**</u>	7. k ()		
33333			JHMM1 (2/98		Whis o post	07/27/99		
			At thurst 141A					

UTAH ATTACHMENT

A rider is attached to the policy that requires the insurer to notify the Division whenever substantive changes are made in the policy including any termination or failure to renew.